



000061142

INTEROFFICE MEMORANDUM

Rocky Flats Environmental Technology Site P.O. Box 464 Golden, Colorado 80402-0464 Phone: (303) 968-2677

DATE:

March 26, 1996

TO:

D. R. Pierson, Waste Storage and Disposal, Bldg. T130B, X3190

FROM:

J. E. Law, Sitewide Actions, Bldg. T893A, X4842

SUBJECT:

DRAIN IDENTIFICATION STUDY INSPECTION OF THE BUILDING 666 DRAIN SYSTEM -

JEL-046-96

The National Pollutant Discharge Elimination System/Federal Facilities Compliance Agreement between the Environmental Protection Agency and the Department of Energy/Rocky Flats Field Office requires Rocky Flats Environmental Technology Site (Site) to "review foundation footing drains where hazardous materials could be introduced into the sanitary sewer system" and to "review other possible sources of hazardous or otherwise inappropriate influents to the sanitary sewer system." The Drain Identification Study (DIS) project was developed to address these requirements by inspecting drain systems in buildings throughout the Site. The DIS is an internal assessment developed to minimize the potential for Clean Water Act violations by revealing possible pathways for inadvertent or inappropriate release of hazardous substances to the sanitary sewer system.

DIS personnel performed inspections of Building 666 drainage systems and identified no potential risk to the sanitary sewer system. The attached documents provide a room-by-room summary of the DIS inspections: (1) Drains and Pathways Inspection Report listing each room and the observations made; (2) Foundation Drain Data Sheet showing available foundation drain information. DIS observations were current as of the inspection dates and the dates can be found in the attached documents.

If you have any questions or need additional information call Frank Rukavina at extension 7370/D5323 or Doug Watson at extension 2143/D0876.

DRW:dq!

Attachments: As Stated

cc:

K. M. Motyl

A. M. Parker

F. Rukavina

D. R. Watson

ER Records Center (2)

RMRS Records

A MAR 1996

RECEIVED

RECORDS CENTER

A STATE OF THE COLUMN TO SELECT THE COLUMN TO SELECT THE COLUMN THE COLUMN TO SELECT THE COLUMN THE COLUM

22.015.F

ADMIN RECCRD

DRAINS and PATHWAYS SUMMARY BUILDING 666

ions		(
Comments/Recommendations	No drawings available						
FL FL Trenches PEN Cracks /Pits							
Cracks	ž						
F 원							
Comments	No drawings available						
WF			0				
UL SS PW UL Open Funnel WF FLDR Sumps Sumps Sumps Fipe Drain		L	٥				
8 8			0				
Sumps			٥			,	
PW Sumps			0				
Sumps			0				
JU. FLOR			0				
PW FLDR			0				
SS FLDR			0				
UL. Sinks			0 0 0				
PW Sinks			0				
Sinks			0		٥		
Drains	2						_
RCA	'n		For		1 For		
* wo	8		unter		ante		
Date Room * RCA Drains SS PW UL SS PW # Sinks Sinks FLDR FLDR	Aar-96 10		Drains Accounted For		ns Acco		•
	Natson/Lusero 4-Mar-96 100		Drai	-	Total Drains Accounted For		
Inspector	Watson/L		ľ		T		

· Page 1 of 1

BUILDING FOUNDATION DRAIN DATA SHEET BUILDING NO. Cbb

		BUILDING NO.	•
	SOURCE	COMMENTS	SIGNITURE/DATE
	DRAWING SEARCH		
	INTERVIEWS		
	96-85-5	pulation representative	
))	laten c	
	FOUND, DR. REPORT	no reference to this	
	·	٠,٧	
	96-88-8	\supset	
		(5 - +10 - 10 C)	
	FIELD INSPECTION		
,			
	OTHER		Att JEL Pag
· · · · · · · · · · · · · · · · · · ·	,		achmer -046-9 e 1 of
			nt #2
<u> </u>			

2